



Hunters Point Radiological Program Update

Hunters Point Naval Shipyard BCT Meeting August 29, 2013



Overview




Radiological Project Work Overview

- Current Project Map
- Parcel C
 - Phase-II SS/SD Removal Update
 - Ship Berth Survey Status
 - Building 253 and 211 Activities
- Parcel D-1
- FSS Report Status Update
- New Contract to Remove Parcel E SS/SD lines



2013 Radiological Projects







Parcel C - Phase II SS/SD Removals




Parcel C SS/SD line removal:

- Phase II 13,000 of 14,300 linear feet of SS/SD lines (91%) and 27,867 cubic yards have been excavated.
- Total of 24 Trench Units Excavated to date:
 - 10 Backfilled/restored
 - 6 Definitive data under review with RASO
 - 4 Awaiting definitive data results
 - 4 Undergoing sampling, survey, and/or remediation



Parcel C Phase II Excavated Trench Units







Parcel C - Ship Berth Surveys




Ship Berths:

- Survey Unit 2 Definitive data under review with RASO
- Survey Units 6, 7, 8, and 9 Survey Complete; awaiting definitive data results
- Survey Units 1, 3, 4 and 5 Undergoing characterization sampling and remediation (Max. concentrations shown)
 - SU-1 2.03 pCi/g Ra-226
 - SU-3 0.23 pCi/g Cs-137
 - SU-4 0.19 pCi/g Cs-137
 - SU-5 0.40 pCi/g Cs-137
 - 1.77 pCi/g Ra-226
- Survey Units 10 through 13 Surveys in process



Parcel C - Phase II Ship Berths







Field Activities in Parcel C Phase II





Remediating soil at Ship Berth SU 4



Labeling/marking bin for transfer to TES



Post-remediation sample locations at Ship Berth SU 4




Preparing for FSS sample collection at TU 335



Radiological Survey of Buildings 253 and 211



- Continue characterization of interior drain lines
- Continue the removal and survey of ventilation system
 - ➤ 50% complete
- Continued asbestos abatement and encapsulation





Field Activities in Buildings 253 and 211





Removing section of ventilation duct on 3rd floor of Building 253



Collecting sediment sample from a 1st floor drain line clean out



Scanning the removed section of ventilation duct work



Collecting sediment from a 3rd flooor drain line clean out



Parcel D-1 Phase I & II




- Phase I
 - Gun Mole Pier
 - Additional field work to perform Strontium-90 remediation completed. Sample results satisfactory. FSS report to be issued Draft on September 5
 - Phase I RACR
 - Draft to be sent Sept 10
 - Confirmation samples
 - 3 FSS reports awaiting CDPH RURR letter (383, 313/313A/322, and South Pier). Confirmation samples submitted.
- Phase II
 - Final Execution Plan issued Aug 5. Design Plan scheduled for Sept 4
 - Mobilization of personnel and equipment scheduled for Sept 5



FSS Report Status








New Work in Parcel E



TtEC was awarded a contract to remove 7,600-LF of Parcel E sanitary sewer and storm drain lines.

Draft Work Plan for Regulatory Review in late October.





Building 518 Sand



- Recommendation
 - Reuse the material as a base material for surface land capping of areas at HPNS
 - Dispose as non-LLRW
- Letter report sent July 10
- Navy requested comments/concurrence
 by August 9 May we proceed with our recommendations?



Note the color of the sand compared to the SS trench material which has been approved for backfill





Comments, Questions, Concerns ???